

**Ningbo GSK Automobile Parts Co., Ltd.**  
**offers all brands of automotive replacement parts.**



**Clock Spring AirBag  
Spiral Cable  
CATALOG**

**Ningbo GSK Automobile Parts Co., Ltd.**

Mail: [info@gskauto.com](mailto:info@gskauto.com) Phone: 0086-13685890381 WhatsApp: +8613454743254  
[WWW.GSKAUTO.COM](http://WWW.GSKAUTO.COM)

# Clock Spring Spiral Cable



| GSK Code   | Product Name                     | OEM/Model   | Brand of Use | Product Description                                 |
|------------|----------------------------------|-------------|--------------|---|
| GSKCSCV001 | Clock Spring AirBag Spiral Cable | 61319129499 | BMW          | BMW E60 E63 E65 760li 745li 645ci 545i M6 650i 550i |
| GSKCSCV002 | Clock Spring AirBag Spiral Cable | 61318976394 | BMW          | BMW 5ER 6 Series E60 E61 E63 E64                    |
| GSKCSCV003 | Clock Spring AirBag Spiral Cable | 61319122509 | BMW          | BMW E90/E91/E92/E93 3-Series                        |
| GSKCSCV004 | Clock Spring AirBag Spiral Cable | 61318379091 | BMW          | E38 E39 E46 E53                                     |
| GSKCSCV005 | Clock Spring AirBag Spiral Cable | A1714640918 | Mercedes     | S-Class W220 W215                                   |
| GSKCSCV006 | Clock Spring AirBag Spiral Cable | 1681600049  | Mercedes     | Truck   |
| GSKCSCV007 | Clock Spring AirBag Spiral Cable | 7701048917  | Renault      | Espace Laguna Sport Tourer                          |
| GSKCSCV008 | Clock Spring AirBag Spiral Cable | 84306-50190 | Lexus        | LX570 LS600HL LS460                                 |
| GSKCSCV009 | Clock Spring AirBag Spiral Cable | 84306-09020 | Toyota       | Camry Hybrid ACV51                                  |
| GSKCSCV010 | Clock Spring AirBag Spiral Cable | 84306-06180 | Toyota       | Corolla Camry RAV4 NEW                              |
| GSKCSCV011 | Clock Spring AirBag Spiral Cable | 84306-06210 | Toyota       | Aurion Camry Corolla Reiz Single                    |
| GSKCSCV012 | Clock Spring AirBag Spiral Cable | 84306-06140 | Toyota       | Camry RAV4  |
| GSKCSCV013 | Clock Spring AirBag Spiral Cable | 84306-0K050 | Toyota       | Hilux Yaris Corolla Camry Vois                      |
| GSKCSCV014 | Clock Spring AirBag Spiral Cable | 84306-02190 | Toyota       | Corolla Yaris VIOS                                  |
| GSKCSCV015 | Clock Spring AirBag Spiral Cable | 84306-0D021 | Toyota       | Soluna Vois AXP4# SCP4# Corolla ZZE122              |
| GSKCSCV016 | Clock Spring AirBag Spiral Cable | 84306-52020 | Toyota       | Yaris Echo Rav4 Corolla                             |
| GSKCSCV017 | Clock Spring AirBag Spiral Cable | 84306-52050 | Toyota       | Corolla RAV4 Estima Noah Wish                       |
| GSKCSCV018 | Clock Spring AirBag Spiral Cable | 84306-0K020 | Toyota       | Hilux Fortuner Innova VIGO Alphard                  |
| GSKCSCV019 | Clock Spring AirBag Spiral Cable | 84306-60080 | Toyota       | 4Runner FJ Cruiser Land Cruiser LX470               |
| GSKCSCV020 | Clock Spring AirBag Spiral Cable | 84306-60090 | Toyota       | Land Cruiser 100 single                             |
| GSKCSCV021 | Clock Spring AirBag Spiral Cable | 84306-58011 | Toyota       | Avensis Verso Picnic Camry New Previa Alphard       |
| GSKCSCV022 | Clock Spring AirBag Spiral Cable | 84306-12070 | Toyota       | 4Runner Camry Celica RAV4 Prius Prado 3400          |
| GSKCSCV023 | Clock Spring AirBag Spiral Cable | 84306-33080 | Toyota       | 4Runner Sienna Camry Scion xB                       |
| GSKCSCV024 | Clock Spring AirBag Spiral Cable | 84306-0P010 | Toyota       | 05-10 Reiz GRX122 Highlander                        |
| GSKCSCV025 | Clock Spring AirBag Spiral Cable | MR583930    | Mitsubishi   | Lancer Outlander L200                               |
| GSKCSCV026 | Clock Spring AirBag Spiral Cable | CA800014-1  | Mitsubishi   | Pajero V31/V33                                      |
| GSKCSCV027 | Clock Spring AirBag Spiral Cable | A00368030   | Mitsubishi   | Pajero CS10   |
| GSKCSCV028 | Clock Spring AirBag Spiral Cable | 8619A015    | Mitsubishi   | Pajero V73 NEW                                      |
| GSKCSCV029 | Clock Spring AirBag Spiral Cable | 8619A016    | Mitsubishi   | Zinger no cruise                                    |
| GSKCSCV030 | Clock Spring AirBag Spiral Cable | 8619A017    | Mitsubishi   | Zinger include cruise                               |



# Clock Spring Spiral Cable



| GSK Code   | Product Name                     | OEM/Model                     | Brand of Use | Product Description                    |
|------------|----------------------------------|-------------------------------|--------------|--|
| GSKCSCV031 | Clock Spring AirBag Spiral Cable | 8619A018                      | Mitsubishi   | Lancer Outlander Eclipse               |
| GSKCSCV032 | Clock Spring AirBag Spiral Cable | MB953170                      | Mitsubishi   | Montero Sport 97-99                    |
| GSKCSCV033 | Clock Spring AirBag Spiral Cable | MB953169                      | Mitsubishi   | Montero Pajero V33                     |
| GSKCSCV034 | Clock Spring AirBag Spiral Cable | SW609636                      | Mitsubishi   | Montero Pajero V33 V43 V45             |
| GSKCSCV035 | Clock Spring AirBag Spiral Cable | 8619A167                      | Mitsubishi   | Outlander Sport ASX                    |
| GSKCSCV036 | Clock Spring AirBag Spiral Cable | CA240081                      | Mitsubishi   | CS6                                    |
| GSKCSCV037 | Clock Spring AirBag Spiral Cable | MR979369                      | Mitsubishi   | Colt 2004-2012                         |
| GSKCSCV038 | Clock Spring AirBag Spiral Cable | SW803816                      | Mitsubishi   | Pajero V3 Lingyue                      |
| GSKCSCV039 | Clock Spring AirBag Spiral Cable | 77900-SNA-K02                 | Honda        | Civic Accord                           |
| GSKCSCV040 | Clock Spring AirBag Spiral Cable | 77900-SNA-K52                 | Honda        | Civic VRV 2007-2012                    |
| GSKCSCV041 | Clock Spring AirBag Spiral Cable | 77900-SDA-Y21                 | Honda        | 03-07 Accord CM5                       |
| GSKCSCV042 | Clock Spring AirBag Spiral Cable | 77900-SDA-Y01                 | Honda        | Accord VII 7 2.0 2003-2007             |
| GSKCSCV043 | Clock Spring AirBag Spiral Cable | 77900-TA0-H12                 | Honda        | Accord 08-11 Jazz Odyssey              |
| GSKCSCV044 | Clock Spring AirBag Spiral Cable | 77900-S84-G11                 | Honda        | Accord 1998-2000 & Prelude 1999-2001   |
| GSKCSCV045 | Clock Spring AirBag Spiral Cable | 77900-SAA-G51                 | Honda        | Fit Hatchback Jazz City 2003-2008      |
| GSKCSCV046 | Clock Spring AirBag Spiral Cable | 77900-SEN-H01                 | Honda        | Jazz / City 2003-2007 03-05 Fit Saloon |
| GSKCSCV047 | Clock Spring AirBag Spiral Cable | 77900-TF0-E91                 | Honda        | CITY 2009-2011                         |
| GSKCSCV048 | Clock Spring AirBag Spiral Cable | 77900-TA0-H21                 | Honda        | 08-11 Accord CP1 2 3                   |
| GSKCSCV049 | Clock Spring AirBag Spiral Cable | 77900-SFE-Q01 / 77900-SWA-Q01 | Honda        | Odyssey Accord 05-06                   |
| GSKCSCV050 | Clock Spring AirBag Spiral Cable | 77900-S3N-Q03                 | Honda        | Accord Odyssey 1999 - 2001             |
| GSKCSCV051 | Clock Spring AirBag Spiral Cable | 77900-TF0-E11                 | Honda        | CITY FIT 1.8                           |
| GSKCSCV052 | Clock Spring AirBag Spiral Cable | 77900-SWA-U51                 | Honda        | CR-V 07-11                             |
| GSKCSCV053 | Clock Spring AirBag Spiral Cable | 77900-S9A-E51                 | Honda        | CR-V 05-06                             |
| GSKCSCV054 | Clock Spring AirBag Spiral Cable | 77900-T6P-B11                 | Honda        | Crider 12PINS                          |
| GSKCSCV055 | Clock Spring AirBag Spiral Cable | 77900-TRO-B21                 | Honda        | New Accord 18Pins                      |
| GSKCSCV056 | Clock Spring AirBag Spiral Cable | 25567-EV06E                   | Nissan       | Sylphy/Tiida/Livina                    |
| GSKCSCV057 | Clock Spring AirBag Spiral Cable | 25560-JD003                   | Nissan       | Qashqai Versa Murano                   |
| GSKCSCV058 | Clock Spring AirBag Spiral Cable | 25554-3DN0A                   | Nissan       | New Tiida                              |
| GSKCSCV059 | Clock Spring AirBag Spiral Cable | 25567-AU025                   | Nissan       | Tiida R8 Wireless                      |
| GSKCSCV060 | Clock Spring AirBag Spiral Cable | 25554-4M425                   | Nissan       | Almera Pulser N16 Sunny G10            |

# Clock Spring Spiral Cable



| GSK Code   | Product Name                     | OEM/Model         | Brand of Use | Product Description                           |
|------------|----------------------------------|-------------------|--------------|---|
| GSKCSCV061 | Clock Spring AirBag Spiral Cable | B5554-JP00A       | Nissan       | Teana Murano Leaf Juke 370Z G37               |
| GSKCSCV062 | Clock Spring AirBag Spiral Cable | B5554-3AW9A       | Nissan       | New Sunny N17Z Tiida C12Z                     |
| GSKCSCV063 | Clock Spring AirBag Spiral Cable | 25567-VW000/9W110 | Nissan       | Teana J31 QR20DE VQ23DE VQ35D                 |
| GSKCSCV064 | Clock Spring AirBag Spiral Cable | B5567-CY70A       | Nissan       | 350Z BLUEBIRD SYLPHY                          |
| GSKCSCV065 | Clock Spring AirBag Spiral Cable | 25567-EA000       | Nissan       | Frontier Pathfinder                           |
| GSKCSCV066 | Clock Spring AirBag Spiral Cable | 25554-W6600       | Nissan       | Zhengzhou Nissan Oting                        |
| GSKCSCV067 | Clock Spring AirBag Spiral Cable | 25554-VK025       | Nissan       | Pathfinder 2001 - 2003 V6 Paladin Pick Up d22 |
| GSKCSCV068 | Clock Spring AirBag Spiral Cable | HMCA-66-CS0       | Mazda        | Haima Family 2                                |
| GSKCSCV069 | Clock Spring AirBag Spiral Cable | FA02-66-CS0W1     | Mazda        | Haima Family 3                                |
| GSKCSCV070 | Clock Spring AirBag Spiral Cable | GJ6E-66-CS0       | Mazda        | Mazda 6                                       |
| GSKCSCV071 | Clock Spring AirBag Spiral Cable | N066-66-CS0W1     | Mazda        | Happin(Haifuxing)                             |
| GSKCSCV072 | Clock Spring AirBag Spiral Cable | BBP3-66-CS0       | Mazda        | Mazda 3                                       |
| GSKCSCV073 | Clock Spring AirBag Spiral Cable | SA30-66-CS0       | Mazda        | Knight  |
| GSKCSCV074 | Clock Spring AirBag Spiral Cable | D651-66-CS0       | Mazda        | Mazda 2 Demio                                 |
| GSKCSCV075 | Clock Spring AirBag Spiral Cable | GJ6E-66-1B1       | Mazda        | MAZDA 6 CX-9 RX-8 SPEED 6                     |
| GSKCSCV076 | Clock Spring AirBag Spiral Cable | 96626530          | Buick        | Excele 1.6 KP(pr)                             |
| GSKCSCV077 | Clock Spring AirBag Spiral Cable | 96387578          | Buick        | Excele 1.8 PT                                 |
| GSKCSCV078 | Clock Spring AirBag Spiral Cable | 96815291          | Buick        | New Excele JK                                 |
| GSKCSCV079 | Clock Spring AirBag Spiral Cable | 25947772          | Buick        | Lacrosse ZJ 2.4                               |
| GSKCSCV080 | Clock Spring AirBag Spiral Cable | 25947775          | Buick        | Regal Verano                                  |
| GSKCSCV081 | Clock Spring AirBag Spiral Cable | 96814006/007      | Chevrolet    | Epica   |
| GSKCSCV082 | Clock Spring AirBag Spiral Cable | 96486299          | Chevrolet    | Lova New                                      |
| GSKCSCV083 | Clock Spring AirBag Spiral Cable | 9007425           | Chevrolet    | Lova  |
| GSKCSCV084 | Clock Spring AirBag Spiral Cable | 9017144           | Chevrolet    | Sail  |
| GSKCSCV085 | Clock Spring AirBag Spiral Cable | 20817720          | Chevrolet    | Cruze   |
| GSKCSCV086 | Clock Spring AirBag Spiral Cable | 20817718          | Chevrolet    | Cruze High                                    |
| GSKCSCV087 | Clock Spring AirBag Spiral Cable | 20794271          | Chevrolet    | Captiva High                                  |
| GSKCSCV088 | Clock Spring AirBag Spiral Cable | 96628697          | Chevrolet    | Captiva Low                                   |
| GSKCSCV089 | Clock Spring AirBag Spiral Cable | 1KO 959 653C      | Volkswagen   | GOLF GTI JETTA BORA RABBIT Sagitar            |
| GSKCSCV090 | Clock Spring AirBag Spiral Cable | 1KO 959 653B      | Volkswagen   | Magotan                                       |
| GSKCSCV091 | Clock Spring AirBag Spiral Cable | 18D 595 653       | Volkswagen   | Passat New Bora                               |



# Clock Spring Spiral Cable



| GSK Code   | Product Name                     | OEM/Model         | Brand of Use | Product Description                                   |
|------------|----------------------------------|-------------------|--------------|---|
| GSKCSCV092 | Clock Spring AirBag Spiral Cable | L1JD 959 635E     | Volkswagen   | Jetta 03  |
| GSKCSCV093 | Clock Spring AirBag Spiral Cable | L1GD 959 653      | Volkswagen   | Jetta 05  |
| GSKCSCV094 | Clock Spring AirBag Spiral Cable | 33D 959 653A      | Volkswagen   | Santana 3000  |
| GSKCSCV095 | Clock Spring AirBag Spiral Cable | 18D 959 653       | Skoda        | Fabia   |
| GSKCSCV096 | Clock Spring AirBag Spiral Cable | 93490-2H300       | Hyundai      | Elantra High 08-11                                    |
| GSKCSCV097 | Clock Spring AirBag Spiral Cable | 93490-2H200       | Hyundai      | Elantra Low 06-11                                     |
| GSKCSCV098 | Clock Spring AirBag Spiral Cable | 93490-38001       | Hyundai      | Sonata  |
| GSKCSCV099 | Clock Spring AirBag Spiral Cable | 93490-2E000       | Hyundai      | Tucson  |
| GSKCSCV100 | Clock Spring AirBag Spiral Cable | 93490-2D000/26000 | Hyundai      | Elantra Matrix Lavita 1999-Up                         |
| GSKCSCV101 | Clock Spring AirBag Spiral Cable | 93490-2M000       | Hyundai/Kia  | Kia Forte Tucson Sportage IX35 High Sportage Low      |
| GSKCSCV102 | Clock Spring AirBag Spiral Cable | 93490-2M300       | Hyundai      | Tucson IX35 2010-2013 low                             |
| GSKCSCV103 | Clock Spring AirBag Spiral Cable | 93490-4E120       | Hyundai      | IX35 Wireless   |
| GSKCSCV104 | Clock Spring AirBag Spiral Cable | 93490-3J000       | Hyundai      | Veracruz  |
| GSKCSCV105 | Clock Spring AirBag Spiral Cable | 93490-3K600       | Hyundai      | Sonata 04-13 Single Wire                              |
| GSKCSCV106 | Clock Spring AirBag Spiral Cable | 93490-3K620       | Hyundai      | Sonata 04-14 Dual Wire                                |
| GSKCSCV107 | Clock Spring AirBag Spiral Cable | 93490-2U000       | Hyundai      | Verna   |
| GSKCSCV108 | Clock Spring AirBag Spiral Cable | 93490-1G210       | Hyundai/Kia  | Accent 2005-10<br>Kia Rio 05-06                       |
| GSKCSCV109 | Clock Spring AirBag Spiral Cable | 93490-1E300       | Hyundai/Kia  | Accent Kia K5   |
| GSKCSCV110 | Clock Spring AirBag Spiral Cable | 93490-3R110       | Hyundai/Kia  | Elantra<br>Kia Cadenza K3 K5 K9                       |
| GSKCSCV111 | Clock Spring AirBag Spiral Cable | 93490-3S110       | Hyundai      | Elantra 2011-2015<br>Sonata 2010-2014                 |
| GSKCSCV112 | Clock Spring AirBag Spiral Cable | 93490-3S010       | Hyundai      | Santa Fe New Wireless                                 |
| GSKCSCV113 | Clock Spring AirBag Spiral Cable | 93490-3Q120       | Hyundai      | Santa Fe New Dual Wire                                |
| GSKCSCV114 | Clock Spring AirBag Spiral Cable | 93490-2G400       | Hyundai/Kia  | Santa Fe 05-12 Single Wire Kia Carens<br>Canada 05-Up |
| GSKCSCV115 | Clock Spring AirBag Spiral Cable | 93490-2G500       | Hyundai/Kia  | Santa Fe Dual Wire Kia Optima 2006 - 2010             |

# Clock Spring Spiral Cable



| GSK Code   | Product Name                     | OEM/Model                        | Brand of Use | Product Description                             |
|------------|----------------------------------|----------------------------------|--------------|---|
| GSKCSCV116 | Clock Spring AirBag Spiral Cable | 93490-2M410                      | Hyundai/Kia  | Hyundai Tuscon IX35 Dual Wire<br>Kia Soul Forte |
| GSKCSCV117 | Clock Spring AirBag Spiral Cable | 93490-2P170                      | Kia          | Sorento Single Wire                             |
| GSKCSCV118 | Clock Spring AirBag Spiral Cable | 93490-2F000                      | Kia          | Cerato/Forte                                    |
| GSKCSCV119 | Clock Spring AirBag Spiral Cable | 93490-22000                      | Hyundai/Kia  | Accent 1995-1999 Rio                            |
| GSKCSCV120 | Clock Spring AirBag Spiral Cable | 93490-2M500                      | Kia          | Forte   |
| GSKCSCV121 | Clock Spring AirBag Spiral Cable | 3774200U2010                     | JAC          | TONGYUE   |
| GSKCSCV122 | Clock Spring AirBag Spiral Cable | 3774200U8010                     | JAC          | J2 Heyue  |
| GSKCSCV123 | Clock Spring AirBag Spiral Cable | 93410-V2090                      | JAC          | Refine Rein                                     |
| GSKCSCV124 | Clock Spring AirBag Spiral Cable | 3774200U7150                     | JAC          | Bingyue   |
| GSKCSCV125 | Clock Spring AirBag Spiral Cable | 83196-FG010                      | Subaru       | Forester Outback Legacy                         |
| GSKCSCV126 | Clock Spring AirBag Spiral Cable | 83116-FE010                      | Subaru       | Impreza STI Forester 04                         |
| GSKCSCV127 | Clock Spring AirBag Spiral Cable | 83196-AG010                      | Subaru       | Outback 03-09 Legacy                            |
| GSKCSCV128 | Clock Spring AirBag Spiral Cable | 83196-AJ010                      | Subaru       | Outback 10-12                                   |
| GSKCSCV129 | Clock Spring AirBag Spiral Cable | 83196-FG020                      | Subaru       | Impreza & Forester 2008-2010                    |
| GSKCSCV130 | Clock Spring AirBag Spiral Cable | 68193280AB                       | Jeep         | Wrangler JK 2007 - 2016                         |
| GSKCSCV131 | Clock Spring AirBag Spiral Cable | 37480-                           | Suzuki       | Swift SX4 Alto                                  |
| GSKCSCV132 | Clock Spring AirBag Spiral Cable | 37480-843A0-000                  | Suzuki       | Alto  |
| GSKCSCV133 | Clock Spring AirBag Spiral Cable | 4M5T14A664AB-Z                   | Ford         | Focus MK2 C-Max Transit                         |
| GSKCSCV134 | Clock Spring AirBag Spiral Cable | 6G9T14A664BD-Z                   | Ford         | Mondeo High                                     |
| GSKCSCV135 | Clock Spring AirBag Spiral Cable | AG9T14A664AC-Z                   | Ford         | Mondeo Low                                      |
| GSKCSCV136 | Clock Spring AirBag Spiral Cable | DK4966CS0A-Z /<br>8A6T-14A664-AB | Ford         | Fiesta MK6 MK7 New                              |
| GSKCSCV137 | Clock Spring AirBag Spiral Cable | 1S7T14A664AC-Z                   | Ford         | Mondeo 3  |
| GSKCSCV138 | Clock Spring AirBag Spiral Cable | CV6T-14A66A-AA                   | Ford         | Escape 13-15                                    |
| GSKCSCV139 | Clock Spring AirBag Spiral Cable | DG9T-14A664-<br>CAW              | Ford         | Mondeo 13                                       |

# Clock Spring Spiral Cable

