



NINGBO GSK AUTOMOBILE PARTS CO., LTD.
Grow with Supreme Quality

**YOUR TRUSTED SOURCE FOR
REPLACEMENT PARTS
FOR ALL MAJOR AUTOMOTIVE BRANDS**

SPARK PLUG CATALOG



+8613685890381 +8613454743254 info@gskauto.com www.gskauto.com

Aiyimei Building, South Business District, Yinzhou Shounan Street, Ningbo, Zhejiang, China

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|-------------------------|--------------|-----------------------------------|
| GSKSP001 | Spark Plug | 90919-01164 / K16RU11 | DENSO | Corolla |
| GSKSP002 | Spark Plug | 90919-01166 / K20R-U | DENSO | Vela1.6L、Vizhi1.4 Xiali1.4 |
| GSKSP003 | Spark Plug | 90919-01176 / K16R-U | DENSO | 4Runner Pickup Scion xB LX450 |
| GSKSP004 | Spark Plug | PK20R11 / 90919-01178 | DENSO | Camry 2.4 |
| GSKSP005 | Spark Plug | GSKSP005 / 90919-01184 | DENSO | Toyota Yaris Rav4 Camry Mark2 Mr2 |
| GSKSP006 | Spark Plug | 90919-01191 / SK20HR11 | DENSO | GRJ150 URJ200 URJ150 TRJ150 |
| GSKSP007 | Spark Plug | 90919-01192 / K16TR11 | DENSO | VZJ90/FJ100 |
| GSKSP008 | Spark Plug | 90919-01235 / K20HR-U11 | DENSO | GRJ120 GRJ200 |
| GSKSP009 | Spark Plug | 90919-01194 / PK20TR11 | DENSO | Camry 2.0/3400 |
| GSKSP010 | Spark Plug | 90919-01198 / K20TR11 | DENSO | Camry |
| GSKSP011 | Spark Plug | 90919-01210 / SK20R11 | DENSO | Camry/RAV4/Vios1.3 |
| GSKSP012 | Spark Plug | 90919-01221 / SK20BGR11 | DENSO | Lexus |
| GSKSP013 | Spark Plug | 90919-01230 / SK20BR11 | DENSO | Camry、Prius、RAV4 |
| GSKSP014 | Spark Plug | 90919-01233 / SK16HR11 | DENSO | Highlander |
| GSKSP015 | Spark Plug | 90919-01217 / SK16R11 | DENSO | Vios1.3 Yaris |
| GSKSP016 | Spark Plug | 90919-01240 / SK16R11 | DENSO | 12 Camry/08 Vios |
| GSKSP017 | Spark Plug | 90919-01247 / FK20HR11 | DENSO | Crown/Reiz |
| GSKSP018 | Spark Plug | 90919-01253 / SC20HR11 | DENSO | Corolla/New Corolla/Vios 1.6 |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|---------------------------|--------------|-------------------------------------|
| GSKSP019 | Spark Plug | 90048-51188 / SXU22PR9 | DENSO | Vios |
| GSKSP020 | Spark Plug | 90919-YZZAD / K16-U | DENSO | TOYOTA LAND CRUISER YARIS 4 RUNNER |
| GSKSP021 | Spark Plug | 90919-YZZAC / Q20-U11 | DENSO | CAMRY CELICA |
| GSKSP022 | Spark Plug | 90919-YZZAE / K16-U11 | DENSO | Land Cruiser 4.5 24v,4Runner 3.0 v6 |
| GSKSP023 | Spark Plug | 22401-1P116 / PFR6G11 | NGK | CEFIRO NISSAN |
| GSKSP024 | Spark Plug | 22401-53J06 / BKR6EY | NGK | General NISSAN |
| GSKSP025 | Spark Plug | 22401-50Y06 / BKR6E-11 | NGK | Nissan Altima Sentra Infiniti QX4 |
| GSKSP026 | Spark Plug | 22401-20J06 / BKR6E | NGK | Nissan Renault Suzuki VW KIA ROVER |
| GSKSP027 | Spark Plug | 22401-5M015 / PLFR5A-11 | NGK | Teana2.3 NISSAN |
| GSKSP028 | Spark Plug | 22401-5M016 / PLFR5A-11 | NGK | Teana2.3 NISSAN |
| GSKSP029 | Spark Plug | 22401-8H515 / LFR5A-11 | NGK | Sucee NISSAN |
| GSKSP030 | Spark Plug | 22401-ED71B / FXE20HE11 | NGK | Versa/LIVINA/SYLPHY NISSAN |
| GSKSP031 | Spark Plug | 22401-CK81B / LZKAR6AP-11 | NGK | Versa/Tiida NISSAN |
| GSKSP032 | Spark Plug | 22401-ED815 / LZKAR6AP-11 | NGK | Versa/Tiida NISSAN |
| GSKSP033 | Spark Plug | 22401-EW61C / FXE22HR11 | NGK | TEANA3.5 NISSAN |
| GSKSP034 | Spark Plug | 22401-JA01B / DILKAR6A-11 | NGK | X-trail Teana2.5 NISSAN |
| GSKSP035 | Spark Plug | 22401-JD01B / FXE20HR11 | NGK | New TEANA NISSAN |
| GSKSP036 | Spark Plug | 22401-1P114 / PFR4G-11 | NGK | Nissan Quest NISSAN |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|------------------------------|--------------|------------------------------------------------------|
| GSKSP037 | Spark Plug | 22401-1KC1C / DILKAR7C9H | NGK | Nissan Juke Pathfinder Infiniti NISSAN |
| GSKSP038 | Spark Plug | 22401-5M014 / PLFR4A-11 | NGK | 350Z NISSAN |
| GSKSP039 | Spark Plug | 22401-7177 / K7RTCUC | NGK | Zhengzhou Nissan |
| GSKSP040 | Spark Plug | 22401-5960A8 / FR8SEU | NGK | Zhengzhou Nissan |
| GSKSP041 | Spark Plug | 22401-AA570 / PFR5B-11 | NGK | Forester, Legacy2.0Outback2.5L SUBARU |
| GSKSP042 | Spark Plug | 22401-AA630 / ILFR6B | NGK | Forester2.5, Legacy2.0Outback3.0L SUBARU |
| GSKSP043 | Spark Plug | 22401-AA670 / SILFR6A | NGK | Forester2.5T Legacy2.5L 14Outback3.6L SUBARU |
| GSKSP044 | Spark Plug | 22401-AA720 / SILFR6A-11 | NGK | 10 Outback/Legacy/Forester2.0 SUBARU |
| GSKSP045 | Spark Plug | 22401-AA731 / SLFR6A-11 | NGK | Subaru Legacy Outback 10-12 2.5L |
| GSKSP046 | Spark Plug | 22401-AA750 / SILFR6C11 | NGK | Legacy2.0 SUBARU |
| GSKSP047 | Spark Plug | 12290-R62-H01 / IZFR6K11NS | NGK | HONDA 2.0 |
| GSKSP048 | Spark Plug | 12290-R48-H01 / ILZKR7B-11S | NGK | 08Accord 2.4 HONDA |
| GSKSP049 | Spark Plug | 12290-5A2-A01 / DILKAR7G11GS | NGK | 9 Accord HONDA |
| GSKSP050 | Spark Plug | 9807B-5617W / IZFR6K-11 | NGK | RE4 HONDA |
| GSKSP051 | Spark Plug | 9807b-5617P / IFR6K-11 | NGK | Honda Accord Civic CR-V FR-V |
| GSKSP052 | Spark Plug | 9807B-56A7W / IZFR6K13 | NGK | HONDA Cr-Z City Sedan Accord VIII VII 1.4-3.5L 2002- |
| GSKSP053 | Spark Plug | 9807B-561BW / IZFR6K-11S | DENSO | CIVIC/CIIMO/CITY1.8/CRV-2.0 HONDA |
| GSKSP054 | Spark Plug | 1822A002 / IFR6B-K | NGK | PajeroV87/V93/V97 MITSUBISHI |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|--------------------------|--------------|--------------------------------------------------------------------------------------|
| GSKSP055 | Spark Plug | 1822A022 / ILFR7H | NGK | Grandis/Nordic/EVO9 MITSUBISHI |
| GSKSP056 | Spark Plug | 1822A085 / DILFR5A-11 | NGK | Mitsubishi |
| GSKSP057 | Spark Plug | 1822A030 / K16PSR-B8 | DENSO | Outlander EX/Lancer EX(4 Cyl/4B12) MITSUBISHI |
| GSKSP058 | Spark Plug | MS851727 / K16PR-U11 | NGK | Mazda Mitsubishi Nissan |
| GSKSP059 | Spark Plug | MS851351 / BK5E | NGK | Mitsubishi |
| GSKSP060 | Spark Plug | MS851336 / BKR6EGP | NGK | Mitsubishi |
| GSKSP061 | Spark Plug | MN158596 / LZFR6A1 | NGK | 06-12Outlander 2.4L 4G69 04-- Grandis2.4L ASX1.6L 12.11-- 07-11Galant2.4L MITSUBISHI |
| GSKSP062 | Spark Plug | MN163235 / FR5EI | NGK | Outlander EX 4G64S4M 2.407-11) Lancer EX (2.4) MITSUBISHI |
| GSKSP063 | Spark Plug | MN163236 / FR6EI | NGK | Lancer EX1.8/2.0 ASX Outlander MITSUBISHI |
| GSKSP064 | Spark Plug | MN163807 / K20PSR-B8 | NGK | Mitsubishi |
| GSKSP065 | Spark Plug | MS851346 / PFR6M | NGK | Mitsubishi |
| GSKSP066 | Spark Plug | MS851357 / BKR5E-11 | NGK | MITSUBISHI Lancer 1.6 2006- Space Wagon2.4L 04-06 |
| GSKSP067 | Spark Plug | MS851358 / BKR6E-11 | NGK | Galant2.0L/2.4L 2012---MITSUBISHI |
| GSKSP068 | Spark Plug | MD373645 / SK20PR-A11 | DENSO | Mitsubishi |
| GSKSP069 | Spark Plug | MD376962 / PK16PR11 | DENSO | Pajero, Pajero Sport MITSUBISHI |
| GSKSP070 | Spark Plug | MR984943 / SK20PR-A8 | DENSO | V77 MITSUBISHI |
| GSKSP071 | Spark Plug | L3Y2-18-110 / ILTR5A-13G | NGK | New Mazda 6 |
| GSKSP072 | Spark Plug | L3Y4-18-110 / IFR6F-13 | NGK | Old Mazda 6 |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|-------------------------------|--------------|-------------------------------------------|
| GSKSP073 | Spark Plug | PE02-18-110 / FC20HPR8 | DENSO | Mazda |
| GSKSP074 | Spark Plug | ZJ46-18-110 / SK16PR-E13 | DENSO | Mazda |
| GSKSP075 | Spark Plug | 12 12 0 037 244 / ZGR6STE2 | BOSCH | New 7 Series BMW |
| GSKSP076 | Spark Plug | 12 12 0 037 580 / ZR5TPP33 | BOSCH | BMW MINI |
| GSKSP077 | Spark Plug | 12 12 0 037 582 / ZR5EPP33-S | BOSCH | Z4 MINI BMW |
| GSKSP078 | Spark Plug | 12 12 0 037 607 / BR6EQUF | NGK | Old 7 Series BMW |
| GSKSP079 | Spark Plug | 12 12 0 037 663 / LZFR6AP11GS | NGK | 3series,New X series BMW |
| GSKSP080 | Spark Plug | 12 12 2 158 252 / IZFR6H11 | NGK | X1 BMW |
| GSKSP081 | Spark Plug | 12 12 2 158 252 / FR7KPP332 | BOSCH | X1 BMW |
| GSKSP082 | Spark Plug | 12 12 2 158 253 / PLZFR6A-11S | NGK | 5 series BMW |
| GSKSP083 | Spark Plug | 12 12 2 158 253 / FR7NPP332 | BOSCH | 5 series BMW |
| GSKSP084 | Spark Plug | 12 12 0 039 664 / SILZKBR8C8S | NGK | BMW E84 E89 F06 F06N BMW |
| GSKSP085 | Spark Plug | A 004 159 18 03 26 / YR7MPP33 | NGK | Mercedes Benz S350 |
| GSKSP086 | Spark Plug | A 004 159 19 03 26 / F8DPP33 | BOSCH | Mercedes Benz Old S series |
| GSKSP087 | Spark Plug | A 004 159 49 03 / PLKR7A | NGK | Mercedes Benz C series |
| GSKSP088 | Spark Plug | A 004 159 68 03 | NGK | Mercedes Benz Mercedes-Benz C E G S Class |
| GSKSP089 | Spark Plug | A 004 159 75 03 | NGK | Mercedes Benz Mercedes-Benz E-Class CLK |
| GSKSP090 | Spark Plug | A 004 159 64 03 | NGK | Mercedes Benz S600 |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|--------------------------------|--------------|--------------------------------------------------------|
| GSKSP091 | Spark Plug | LR005253 / IFR5N-10 | NGK | LAND ROVER Range Rover Sport02-09Discovery3 05-09 4.4L |
| GSKSP092 | Spark Plug | LR005483 / ILFR6B | NGK | LAND ROVER Freelander2 (2006-) 3.2L gasoline |
| GSKSP093 | Spark Plug | LR025605 / CYFS12YPS | NGK | LAND ROVER Freelander2 Range Rover Evoque 2.0 gasoline |
| GSKSP094 | Spark Plug | LR032080 / ILKAR7C10 | NGK | LAND ROVER Discovery 4 Range Rover 5.0 |
| GSKSP095 | Spark Plug | NLP100290 | NGK | LAND ROVER Discovery 3 |
| GSKSP096 | Spark Plug | LR000604 / AGSF24N | NGK | LAND ROVER Land Rover LR3 Cologne 4.0L V6 |
| GSKSP097 | Spark Plug | 8692071 | BOSCH | VOLVO S60/V70/S80/C70 5 Cyl |
| GSKSP098 | Spark Plug | 8692072 | BOSCH | VOLVO S80 6 Cyl |
| GSKSP099 | Spark Plug | 30751806 | BOSCH | VOLVO S40/V50/S80 5 Cyl |
| GSKSP100 | Spark Plug | 30751805 | BOSCH | VOLVO V70/XC70/S80 6 Cyl |
| GSKSP100 | Spark Plug | 30758130 | BOSCH | VOLVO S80/V70 4 Cyl |
| GSKSP102 | Spark Plug | 30650843 | BOSCH | VOLVO S40 5 Cyl |
| GSKSP103 | Spark Plug | 8#41-101 / ITR4A15 / 12568387 | AC | BUICK old Regal/old GL8 |
| GSKSP104 | Spark Plug | 8#41-103 / IL7R5B11 / 12625058 | AC | BUICK new Regal/new LaCrosse |
| GSKSP105 | Spark Plug | 8#41-985 | AC | BUICK |
| GSKSP106 | Spark Plug | 8#41-108 / ILTR5D / 12620540 | AC | BUICK new Regal 2.0 |
| GSKSP107 | Spark Plug | 8#41-109 / 12622561 | AC | BUICK Cadillac Enclave Park AV |
| GSKSP108 | Spark Plug | 8#41-110 / 12621258 | AC | BUICK |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|-----------------------------|--------------|-----------------------------------------------------|
| GSKSP109 | Spark Plug | 8#41-114 / 12622441 | AC | BUICK |
| GSKSP110 | Spark Plug | R6632 | AC | BUICK |
| GSKSP111 | Spark Plug | 96130723 | BOSCH | BUICK |
| GSKSP112 | Spark Plug | 96307562 | | BUICK |
| GSKSP113 | Spark Plug | 96307729 | | BUICK |
| GSKSP114 | Spark Plug | 9146367 | BOSCH | BUICK |
| GSKSP115 | Spark Plug | 04C 905 616 / GERMANY | BOSCH | VOLKSWAGEN - New Santana |
| GSKSP116 | Spark Plug | 04E 905 612 / GERMANYBOM | NGK / BOSCH | VOLKSWAGEN - New Jetta |
| GSKSP117 | Spark Plug | 06H 905 604 / BKR8EQUA | NGK / BOSCH | VOLKSWAGEN - Magotan New Passat 1.8T |
| GSKSP118 | Spark Plug | 06E 905 611 / F7KPP332U | NGK / BOSCH | VOLKSWAGEN - Audi A6L 2.4 2.7 3.2 |
| GSKSP119 | Spark Plug | 06H 905 611 / 0 241 245 670 | NGK / BOSCH | VOLKSWAGEN - CC/Tiguan, Magotan, Sagitar1.8T 2.0TSI |
| GSKSP120 | Spark Plug | 101 000 033AA / BKUR6ET-10 | NGK / BOSCH | VOLKSWAGEN - Passat B5 Bora 1.8 |
| GSKSP121 | Spark Plug | 101 000 035HJ / BKR6EKUB | NGK / BOSCH | VOLKSWAGEN - A6L 2.8 A6 2.8 2.4 |
| GSKSP122 | Spark Plug | 101 000 063AA / PFR6Q | NGK / BOSCH | VOLKSWAGEN - B5/1.8T A6 2.0T |
| GSKSP123 | Spark Plug | 101 000 036AA / BUR6ET | NGK / BOSCH | VOLKSWAGEN |
| GSKSP124 | Spark Plug | 101 905 601B / K7HER2B0M | NGK / BOSCH | VOLKSWAGEN - Polo 1.4 |
| GSKSP125 | Spark Plug | 101 905 611G / PFR8S8EG | NGK / BOSCH | VOLKSWAGEN - Touareg A8 A4L Q5 |
| GSKSP126 | Spark Plug | 101 905 621B / PFR6W-TG | NGK / BOSCH | VOLKSWAGEN - Q7 3.2 Touareg 4.2L New A6 2.8 |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|--------------------------------|--------------|----------------------------------------------------------------|
| GSKSP127 | Spark Plug | 06H 905 601A / PFR7S8EG | NGK / BOSCH | VOLKSWAGEN - New Passat 2.0T 2014 A6 2.8L |
| GSKSP128 | Spark Plug | 101 905 622 / ILZKR7A | NGK / BOSCH | VOLKSWAGEN - Q7 Touareg 3.6 |
| GSKSP129 | Spark Plug | 101 905 631H / 0 241 245 666 | NGK / BOSCH | VOLKSWAGEN - New Passat,Audi A6L Q5 A4L 2.0T |
| GSKSP130 | Spark Plug | 101 905 631A / F7KPP332U | NGK / BOSCH | VOLKSWAGEN - |
| GSKSP131 | Spark Plug | 101 905 606a / IZKR7B | NGK / BOSCH | VOLKSWAGEN - Q7 3.2 |
| GSKSP132 | Spark Plug | 03C 905 601 / PZFR6R | NGK / BOSCH | VOLKSWAGEN - |
| GSKSP133 | Spark Plug | 101 905 626 / PZFR6R | NGK / BOSCH | VOLKSWAGEN - AUDI A1 A3 VW Golf Jetta Passat SKODA SEAT 1.4TSI |
| GSKSP134 | Spark Plug | SP-411 / AYFS22FM | CHAMPION | FORD - Fiesta |
| GSKSP135 | Spark Plug | SP-432 / AGSF32FM | CHAMPION | FORD - Mondeo |
| GSKSP136 | Spark Plug | SP-479 / AGSF22WM | CHAMPION | FORD - |
| GSKSP137 | Spark Plug | SP-500 AGSF22FM | CHAMPION | FORD - |
| GSKSP138 | Spark Plug | SP-537 / CYFS-12Y-2 | CHAMPION | FORD - Edge 2.0T |
| GSKSP139 | Spark Plug | SP-530 / AYFS-32-R | CHAMPION | FORD - Mondeo |
| GSKSP140 | Spark Plug | SP-493 / AGSF32PM | CHAMPION | FORD - |
| GSKSP141 | Spark Plug | SP-509 / HJFS-24-FP | CHAMPION | FORD -Ford Raptor 5.4 |
| GSKSP142 | Spark Plug | BL3E-12405-CA / CYFS12Y3 | CHAMPION | FORD -New Focus |
| GSKSP143 | Spark Plug | 9S7E-12405-AA / Q6RTP-13 | | FORD - Old Focus |
| GSKSP144 | Spark Plug | 1S7J-12405-EB / AGFS 22 FE 13J | | FORD -CD2.0L |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|----------------------------|--------------|------------------------------------------|
| GSKSP145 | Spark Plug | 6M8G-12405-BB / ILTR5A-13G | | FORD - S-MAX |
| GSKSP146 | Spark Plug | DJ5E-12405-AA / CYFS-12Y-2 | | FORD - Focus III/Stufenheck |
| GSKSP147 | Spark Plug | Z6B7-18-110 / K16P2R13 | | FORD -JNH09/1.5 |
| GSKSP148 | Spark Plug | E4G16-3707110 / RER8WMB | | CHERY New Tiggo |
| GSKSP149 | Spark Plug | A11-3707110CA / K7RTR | | CHERY 473/481 |
| GSKSP150 | Spark Plug | S11-3707100 / F6RTC | | CHERY QQ |
| GSKSP151 | Spark Plug | NLP000130 / PFR6Y | NGK | Roewe |
| GSKSP152 | Spark Plug | 55247855 / IKR9H | NGK | FIAT-1.4T Viaggio、Bravo 08-11、Linea08 |
| GSKSP153 | Spark Plug | 101303-52010000 / K7REP4 | | Trumpchi |
| GSKSP154 | Spark Plug | 101303-51820000 / LKR7FI-8 | | Trumpchi |
| GSKSP155 | Spark Plug | 22401-NE110-C1 / RC8PYCBX | | Luxgen |
| GSKSP156 | Spark Plug | 22401-MP100-H3 / RC8YCC | | Luxgen |
| GSKSP157 | Spark Plug | 77 00 500 155 | | Fiat Iveco Renault 2.5 D 2.8 TD |
| GSKSP158 | Spark Plug | 77 00 500 048 | | Dacia Nissan Renault Suzuki VW KIA ROVER |
| GSKSP159 | Spark Plug | 77 00 500 168 | | AUDI BMW DACIA FORD OPEL PSA RENAULT |
| GSKSP160 | Spark Plug | 18855-10060 / LZKR6B-10E | NGK | HYUNDAI/KIA - Elantra、Verna |
| GSKSP161 | Spark Plug | 18855-10080 / SILZKR6B-11 | NGK | HYUNDAI/KIA - Elantra、Verna |
| GSKSP162 | Spark Plug | 18840-11051 / ILFR5B-11 | NGK | HYUNDAI/KIA - New Santa Fe |

SPARK PLUG



GSKSP-163



GSKSP-164



GSKSP-165



GSKSP-166



GSKSP-167



GSKSP-168



GSKSP-169



GSKSP-170



GSKSP-171



GSKSP-172



GSKSP-173



GSKSP-174



GSKSP-175



GSKSP-176



GSKSP-177



GSKSP-178



GSKSP-179



GSKSP-180

| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|---------------------------|--------------|---------------------------------------|
| GSKSP163 | Spark Plug | 27410-37100 / PFR5N | NGK | HYUNDAI/KIA - Elantra |
| GSKSP164 | Spark Plug | 18829-11050 / ZFR5F11 | NGK | HYUNDAI/KIA - |
| GSKSP165 | Spark Plug | 18854-10080 / RE8MC | NGK | HYUNDAI/KIA - New ELANTRA I30 Verna |
| GSKSP166 | Spark Plug | 18841-11051 / LFR5A-11 | NGK | HYUNDAI/KIA -Sonata 8 |
| GSKSP167 | Spark Plug | 18846-11070 / SILZKR7B-11 | NGK | HYUNDAI/KIA - Sonata 8, Elantra, IX35 |
| GSKSP168 | Spark Plug | 18814-11051 / BKR5ES-11 | NGK | HYUNDAI/KIA - Chollima, Cerato |
| GSKSP169 | Spark Plug | 18814-11051 / BKR5ES-11 | NGK | HYUNDAI/KIA - Chollima, Cerato |
| GSKSP170 | Spark Plug | 18846-10070 / SILZKR7B-11 | NGK | HYUNDAI/KIA -K3, K5,Sportage |
| GSKSP171 | Spark Plug | 18841-11051 / LFR5A-11 | NGK | K2, Sportage |
| GSKSP172 | Spark Plug | IK16 / 5303 | DENSO | Toyota Nissan Honda |
| GSKSP173 | Spark Plug | IK20 / 5304 | DENSO | Toyota Nissan Honda |
| GSKSP174 | Spark Plug | IKH16 / 5343 | DENSO | Toyota Nissan Honda |
| GSKSP175 | Spark Plug | IKH20 / 5344 | DENSO | Toyota Nissan Honda |
| GSKSP176 | Spark Plug | IKH22 / 5345 | DENSO | Toyota Nissan Honda |
| GSKSP177 | Spark Plug | IK20L / 5358 | DENSO | Toyota Nissan Honda |
| GSKSP178 | Spark Plug | VK20 / 5604 | DENSO | Toyota Nissan Honda |
| GSKSP179 | Spark Plug | VK20G / 5641 | DENSO | Toyota Nissan Honda |
| GSKSP180 | Spark Plug | VK20Y / 5620 | DENSO | Toyota Nissan Honda |

SPARK PLUG



GSKSP-181



GSKSP-182



GSKSP-183



GSKSP-184



GSKSP-185



GSKSP-186



GSKSP-187



GSKSP-188



GSKSP-189



GSKSP-190



GSKSP-191



GSKSP-192



GSKSP-193



GSKSP-194



GSKSP-195



GSKSP-196



GSKSP-197



GSKSP-198

| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|--------------------|--------------|---------------------|
| GSKSP181 | Spark Plug | VKH16 / 5617 | DENSO | Toyota Nissan Honda |
| GSKSP182 | Spark Plug | VKH20 / 5618 | DENSO | Toyota Nissan Honda |
| GSKSP183 | Spark Plug | IK20G / 5352 | DENSO | Toyota Nissan Honda |
| GSKSP184 | Spark Plug | K16R-U11 / 3120 | DENSO | Toyota Nissan Honda |
| GSKSP185 | Spark Plug | VFKH16 / 5654 | DENSO | Toyota Nissan Honda |
| GSKSP186 | Spark Plug | PK20PR-P8 / 3245 | DENSO | Toyota Nissan Honda |
| GSKSP187 | Spark Plug | PK20R11 / 3128 | DENSO | Toyota Nissan Honda |
| GSKSP188 | Spark Plug | SC20HR11 / 3444 | DENSO | Toyota Nissan Honda |
| GSKSP189 | Spark Plug | FK20HR11 / / 3426 | DENSO | Toyota Nissan Honda |
| GSKSP190 | Spark Plug | FXE20HR11 / 3439 | DENSO | Toyota Nissan Honda |
| GSKSP191 | Spark Plug | SK20R11 / 3297 | DENSO | Toyota Nissan Honda |
| GSKSP192 | Spark Plug | FXE20HE11 / 3436 | DENSO | Toyota Nissan Honda |
| GSKSP193 | Spark Plug | SK20HR11 / 3421 | DENSO | Toyota Nissan Honda |
| GSKSP194 | Spark Plug | PK20PR11 / 3168 | DENSO | Toyota Nissan Honda |
| GSKSP195 | Spark Plug | DILFR6D11 / 6176 | NGK | |
| GSKSP196 | Spark Plug | IFR5T11 / 4996 | NGK | |
| GSKSP197 | Spark Plug | LZKAR6AP-11 / 6643 | NGK | |
| GSKSP198 | Spark Plug | ITR6F13 / 4477 | NGK | |

SPARK PLUG



| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|-------------------|--------------|------------------------------------------|
| GSKSP199 | Spark Plug | IZFR6K11 / 6994 | NGK | |
| GSKSP200 | Spark Plug | PZFR6R / 5758 | NGK | |
| GSKSP201 | Spark Plug | IZFR6K-11S / 5266 | NGK | |
| GSKSP202 | Spark Plug | IZFR6K13 / 6774 | NGK | |
| GSKSP203 | Spark Plug | ZFR5FIX-11 / 3145 | NGK | |
| GSKSP204 | Spark Plug | ZFR6FIX-11 / 3668 | NGK | |
| GSKSP205 | Spark Plug | BKR6EIX-11 / 4272 | NGK | |
| GSKSP206 | Spark Plug | DCPR7EIX / 3144 | NGK | |
| GSKSP207 | Spark Plug | BKR5EIX-11 / 3184 | NGK | |
| GSKSP208 | Spark Plug | LTR6IX-11 / 6509 | NGK | |
| GSKSP209 | Spark Plug | LFR6AIX-11 / 5416 | NGK | |
| GSKSP210 | Spark Plug | LFR5AIX-11 / 6708 | NGK | |
| GSKSP211 | Spark Plug | ILTR5A-13G / 3811 | NGK | Mazda 3/5/6/8, Besturn, Ruiyi, Mondeo |
| GSKSP212 | Spark Plug | ITR4A15 / 5599 | NGK | |
| GSKSP213 | Spark Plug | SILFR6A11 / 5468 | NGK | |
| GSKSP214 | Spark Plug | ILFR6B / 6481 | NGK | Forester, Legacy, New Passat, S40 |
| GSKSP215 | Spark Plug | PLFR5A-11 / 6240 | NGK | |
| GSKSP216 | Spark Plug | PFR6G-11 / 5555 | NGK | |

SPARK PLUG



GSKSP-217



GSKSP-218



GSKSP-219



GSKSP-220



GSKSP-221



GSKSP-222



GSKSP-223



GSKSP-224



GSKSP-225



GSKSP-226



GSKSP-227



GSKSP-228



GSKSP-229



GSKSP-230



GSKSP-231



GSKSP-232



GSKSP-233



GSKSP-234

| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|-------------------|--------------|---------------------|
| GSKSP217 | Spark Plug | LZFR6AI / 3656 | NGK | |
| GSKSP218 | Spark Plug | IZKR7B / 7563 | NGK | |
| GSKSP219 | Spark Plug | FR6EI / 2687 | NGK | |
| GSKSP220 | Spark Plug | DILKAR6A11 / 9029 | NGK | |
| GSKSP221 | Spark Plug | ILKAR7B11 / 4912 | NGK | |
| GSKSP222 | Spark Plug | ILZKR7A / 1961 | NGK | |
| GSKSP223 | Spark Plug | BK6EIX-11 / 3764 | NGK | |
| GSKSP224 | Spark Plug | LFR5AIX-11 / 4469 | NGK | |
| GSKSP225 | Spark Plug | BPR6EIX-11 / 3665 | NGK | |
| GSKSP226 | Spark Plug | BKR5EIX / 1159 | NGK | |
| GSKSP227 | Spark Plug | BPR6EIX / 3484 | NGK | |
| GSKSP228 | Spark Plug | BPR6EIX / 6637 | NGK | |
| GSKSP229 | Spark Plug | BKR6EIX / 2272 | NGK | |
| GSKSP230 | Spark Plug | PFR6Q / 6458 | NGK | |
| GSKSP231 | Spark Plug | PFR6N-11 / 3546 | NGK | |
| GSKSP232 | Spark Plug | ZFR6FGP / 7100 | NGK | |
| GSKSP233 | Spark Plug | BKR5EGP / 7090 | NGK | |
| GSKSP234 | Spark Plug | BKR6EGP / 7092 | NGK | |

SPARK PLUG



GSKSP-235



GSKSP-236



GSKSP-237



GSKSP-238



GSKSP-239



GSKSP-240



GSKSP-241



GSKSP-242



GSKSP-243



GSKSP-244



GSKSP-245



GSKSP-246



GSKSP-247



GSKSP-248



GSKSP-249



GSKSP-250

| GSK Code | Product Name | OEM/Model | Brand of Use | Product Description |
|----------|--------------|----------------------|--------------|---------------------|
| GSKSP235 | Spark Plug | BKR6E-11 / 2756 | NGK | |
| GSKSP236 | Spark Plug | PFR6W-TG / 5547 | NGK | |
| GSKSP237 | Spark Plug | PZFR5N-11 / 7742 | NGK | |
| GSKSP238 | Spark Plug | IFR5J11 / 7418 | NGK | |
| GSKSP239 | Spark Plug | IFR6J11 / 7658 | NGK | |
| GSKSP240 | Spark Plug | BKR5EIX-11 / 5464 | NGK | |
| GSKSP241 | Spark Plug | BKR5EIX / 6341 | NGK | |
| GSKSP242 | Spark Plug | DCPR7EGP | NGK | |
| GSKSP243 | Spark Plug | DCPR7E / 4415 | NGK | |
| GSKSP244 | Spark Plug | IFR7G-11KS / 7746 | NGK | |
| GSKSP245 | Spark Plug | PFR6Y / 9331 | NGK | |
| GSKSP246 | Spark Plug | SILZKR6B-10E / 93815 | NGK | |
| GSKSP247 | Spark Plug | DILKAR7C9H / 91215 | NGK | |
| GSKSP248 | Spark Plug | DILKAR7G11GS / 91578 | NGK | |
| GSKSP249 | Spark Plug | ILZKR7B-11S / 5787 | NGK | |
| GSKSP250 | Spark Plug | PFR5N-11 / 5838 | NGK | |